

Kalpak Force Push Pull Gauge

Parameter	KFG-01	KFG-02
Test Parameters	Measures Tension and Compression forces.	
Units of Measurement	Programmable as Lb, Kg, N, gms	Fixed as Lb/Kg/N/gms
Tare	Front Panel Tare for easy zero setting and Optional Remote Tare. Front Panel Tare for easy zero setting.	
Automatic Peak Force Memory	Available	Available
Peak Hold/ Instantaneous mode selection	Available	Available
Battery or Ac Operation	Available	Available
General Purpose I/O for External Device Control Suitable for Go-No Go Testing.	Available	-
Built-in Memory	Available	-
Set Point Facility With corresponding Relay Outputs	Optional	-
0-1V or 4-20 mA Linear Output corresponding to Load Value	Optional	Optional
PC Interface	Available	Optional
Serial Printer Interface	Available	Optional