

SPECIFICATIONS

Model / Range	1 Phase and 3 phase input/ output. 40A to 300A per phase
Load Type	Resistive
Self Start	Provided
Protection	Over Head and Current
Controlling method	Phase Angle
Output status Indication	Provided (LED Indication)
Control Input	4-20mA or 0-5V, 0-10V linear or pot meter adjustment
Operating Temperature Humidity	0-50°C / 30 to 90% Rh