

Model	Ratio	Output Torque, kgm	Input Torque, kgm	Stem Dia. (max.), mm	<u>Gearbox Mounting</u> No of Holes X Size X P.C.D., mm
SS25	4:1	25	7	30	4 X M16 X 140
SS50	4:1	50	15	50	4 X M16 X 140
SS75	4:1	75	22	50	4 X M20 X 165
SS100	6:1	100	20	65	4 X M20 X 165
SS150	8:1	150	22	65	8 X M16 X 254
SS200	8:1	200	30	75	8 X M16 X 254
SS400	8:1	400	59	86	8 X M20 X 305
SS400/SGA	32:1	400	17	86	8 X M20 X 305
SS800	8:1	800	117	115	8 X M30 X 350
SS800/SGA	48:1	800	23	115	8 X M30 X 350